

UNSAFE STRUCTURES BOARD AGENDA

MARCH 21, 2013

3:00 PM

COMMISSION MEETING ROOM CITY HALL

100 N. ANDREWS AVENUE

UNSAFE STRUCTURES BOARD

Ordinance: C-75-26

PURPOSE: To establish uniform minimum standards for the occupancy of dwelling, hotel and rooming structures and for the uniform minimum standards for the maintenance of the premises occupied or adjacent to such structures, including vacant lots and the premises of business establishments located in proximity thereto.

If any person decides to appeal any decision made with respect to any matter considered at this public meeting or hearing, he/she will need to ensure that a verbatim record of the proceedings is made, which record includes the testimony and evidence upon which the appeal is to be based.

If you desire auxiliary services to assist in viewing or hearing the meeting or reading agendas and minutes for the meetings, please contact the City Clerk's Office at 954-828-5002 and arrangements will be made to provide these services to you.

Board Members: Michael Weymouth, **Chair** • Joe Holland, **Vice Chair** • John Barranco • Joe Crognale • Pat Hale • Thornie Jarrett • Don Larson • John Phillips • B. George Walker

TWO OR MORE FORT LAUDERDALE CITY COMMISSIONERS OR MEMBERS OF A CITY OF FORT LAUDERDALE ADVISORY BOARD MAY BE IN ATTENDANCE AT THIS MEETING.

COMMUNICATION TO THE CITY COMMISSION WILL BE ADDRESSED AT THE END OF THE HEARING.

Page 1

CITY OF FORT LAUDERDALE AGENDA

UNSAFE STRUCTURES BOARD COMMISSION MEETING ROOM - CITY HALL MARCH 21, 2013

3:00 PM

RETURN HEARING (OLD BUSINESS)

CE07061056 CASE NO:

CASE ADDR: 627 N FEDERAL HWY WATERMAN, EDMUND INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2010) 116.1.1

THE COMMERCIAL BUILDING HAS BEEN SUBSTANTIALLY DAMAGED BY LACK OF MAINTENANCE AND EXPOSURE TO THE ELEMENTS AND HAS BECOME A WINDSTORM HAZARD.

FBC(2010) 116.1.2

WORK WITHOUT PERMITS INCLUDING BUT NOT LIMITED TO INTERIOR DEMOLITION, PLUMBING, ELECTRICAL, MECHANICAL, EXTERIOR DOORS AND GLASS BLOCK HAS COMMENCED.

FBC(2010) 116.2.1.2.1

THE FOLLOWING BUILDING COMPONENTS HAVE OR ARE FAILING, HANGING LOOSE OR LOOSENING:

- 1. STEEL ROOF JOISTS.
- 2. STUCCO.
- 3. LATH.
- 4. EXTERIOR SOFFIT.
- 5. LIGHTING.
- 6. ELECTRICAL WIRES.
- 7. DRYWALL.
- 8. PLASTER.
- 9. WOOD FRAMING.
- 10. WOOD PANELING.

FBC(2010) 116.2.1.2.2

THE ROOF JOISTS AND EXTERIOR SOFFIT OVERHANGS ARE RUSTING OUT AND DETERIORATING.

Page 2

CITY OF FORT LAUDERDALE AGENDA

UNSAFE STRUCTURES BOARD COMMISSION MEETING ROOM - CITY HALL MARCH 21, 2013 3:00 PM

CASE NO: CE11111569 CASE ADDR: 1642 NW 13 CT

OWNER: AMERICAM REAL ESTATE STRATEGIES FUN

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 116.1.1

THE SINGLE FAMILY CBS BUILDING BUILT IN 1952 AND

THE CBS FLORIDA ROOM ADDITION THAT WERE

SUBSEQUENTLY ATTACHED ON 1968 HAVE BECOME UNSAFE. THE BUILDING HAS BEEN SUBSTANTIALLY DAMAGED BY THE ELEMENTS AND IS A FIRE AND WINDSTORM HAZARD. THE

BUILDING DOES NOT CONFORM TO THE MINIMUM

MAINTENANCE STANDARD OF THE FLORIDA BUILDING CODE

OR THE FORT LAUDERDALE MINIMUM HOUSING CODE.

FBC(2010) 116.2.1.2.2

THE ROOF DECK ABOVE THE FLORIDA ROOM IS CAVING INTO THE LIVING SPACE OF THE ADDITION. MANY AREAS OF THE MAIN ROOF ARE LOOSE AS THE FACIA WITH THE SOFFIT. THE DOORS AND WINDOWS FRAMES ARE DAMAGED DUE THAT THE STRUCTURE OF THE FLORIDA ROOM IS NOT

AT PLUMB ANY MORE. THE CEILING MATERIAL, ALONG WITH ELECTRICAL FIXTURES AND CONDUIT ARE BEING DAMAGED BY THE WATER PENETRATION. MILDEW IS GROWING ON THE WALLS AND CEILING SURFACE.

Page 3

CITY OF FORT LAUDERDALE AGENDA

UNSAFE STRUCTURES BOARD COMMISSION MEETING ROOM - CITY HALL MARCH 21, 2013

3:00 PM

HEARING SCHEDULED (NEW BUSINESS)

CASE NO: CE07080354 CASE ADDR: 603 SOLAR ISLE GARCIA, ROSA A INSPECTOR: GERRY SMILEN

VIOLATIONS: FBC(2010) 116.1.1

THE OLD WOOD FRAME SINGLE FAMILY DWELLING THAT WAS CONSTRUCTED IN 1949 HAS BEEN SUBSTATIALLY DAMAGED BY THE ELEMENTS AND HAS BECOME A WINDSTORM HAZARD.

FBC(2010) 116.2.1.2.1

THE FOLLOWING BUILDING COMPONENTS ARE HANGING LOOSE, LOOSENING, OR FALLING:

- 1. EXTERIOR SIDING.
- 2. WOOD WINDOW SASHES.
- 3. WOOD FRAMING.

FBC(2010) 116.2.1.2.2

THE WOODEN EXTERIOR INCLUDING BUT NOT LIMITED TO FRAMING, SIDING AND WIDOW FRAMESIS DETERIORATING DUE TO EXPOSURE TO THE ELEMENTS.

FBC(2010) 116.2.1.2.4

THE FOUNDATION OF THE BUILDING HAS SAGGED EXTREMELY DOWNWARD FROM OVERSTRESSING.

FBC(2010) 116.2.1.2.7

THE SWIMMING POOL CONTAINS STAGNANT WATER AT A LOW LEVEL WITHOUT ANY SIGN OF RECIRCULATION AND FILTRATION.